

How much does a lead-based paint inspect cost?

The cost to analyze client furnished samples (paint chips) for lead content ranges between \$25 and \$50 per sample.

Lead Risk Assessments are sometimes required by insurance companies or in certain rental situations. The cost of a lead risk assessment ranges from \$350 to greater than \$3,000 depending on the size and number of damaged painted surfaces.

Full Lead Inspections involve the evaluation of every surface in a building for LBPs. The cost of a Full LBP inspection ranges between \$2,500 to greater than \$10,000.

Please call us and we can provide you with additional information.