

PAGE 1 of 2 TEC-AN INC. 2137 S. PURDUE OKC, OK 73128 PHONE 405-681-7076 WWW.TEC-AN.COM

## LABORATORY ANALYTICAL REPORT

Paul's Wrecking Company Client: Address: 5555 S. New Hampshire Dr.

Okc. OK 55555

Date Received: 12/1/2015 Date Analyzed: 12/1/2015

**Turn Around:** Standard Tec-An Log #: 15-5555 **Project Name:** 5555 Project/PO #: 55-55 Sampled By: Bill Brasky Date Sampled: 12/1/2015

SAMPLE #	Sample Information Location/Material Description	ASBESTOS COMPONENTS (%)	Non-Asbestos Components (%)	PHYSICAL DESCRIPTION (COLOR/TEXTURES)
1	CEILING PANEL	NONE	CELLULOSE 45 FIBROUS GLASS 15 OTHER 40	OFF-WHITE/FIBROUS
2	CEILING POPCORN TEXTURE	CHRYSOTILE 3	CELLULOSE 15 OTHER 82	OFF-WHITE/MEDIUM
3	CEILING POPCORN TEXTURE	CHRYSOTILE 3	CELLULOSE 15 OTHER 82	OFF-WHITE/MEDIUM
4	CEILING POPCORN TEXTURE	CHRYSOTILE 3	CELLULOSE 15 OTHER 82	OFF-WHITE/MEDIUM
5	SHEETROCK MUD/JOINT COMPOUND	NONE	OTHER 100	WHITE/SOFT
6	CEILING TEXTURE	CHRYSOTILE 3	CELLULOSE 2 OTHER 95	WHITE/SOFT
7	CEILING TEXTURE	CHRYSOTILE 5	CELLULOSE 2 OTHER 98	WHITE/SOFT
8	12X12 VINYL FLOORING	NONE	CELLULOSE 2 FIBROUS GLASS 10 OTHER 88	WHITE/SOFT/SLI-FIBROUS

I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED IN STRICT COMPLIANCE WITH APPLICABLE STANDARDS AND REGULATIONS. EPA TEST METHOD 600/R-93/116

Analyst: Date	12/1/2015	Authorized Signature:
<b>Reported</b> : Remarks	12/1/2013	

This report may not be reproduced, except in full, without written approval of Tec-An, Inc. These results relate only to the items tested and represent analysis of samples submitted by the client. Tec-An, Inc. is not responsible for any errors resulting from improper or incorrect sampling procedures; errors resulting from atmospheric conditions at the time of sampling or during shipment; or errors resulting from shipping conditions All samples will be held for 45 days before disposal.













## Lab Log # 15-5555



PAGE 2 of 2 TEC-AN INC. 2137 S. PURDUE OKC, OK 73128 PHONE 405-681-7076 WWW.TEC-AN.COM

This laboratory uses the standard "Visual Area Estimation" technique of polarized light microscopy (PLM) for determining the quantity of asbestos in a bulk material sample. The analysis of samples containing small amounts of asbestos, less than 10% by weight or fibers shorter than 20 micrometers in length, using this technique may not be accurate. The US Environmental Protection Agency (US EPA) **RECOMMENDS** verification of such analyses by a more reliable method such as the PLM "Point Counting" technique, or in the case of floor tile and short-range chrysotile, the "Analytical Electron Microscopy" techniques. If this service is desired, please contact TEC-AN, Inc. for costs and processing approvals. "Results represent the asbestos analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. This report shall not be reproduced, except in full, without the written consent of TEC-AN, Inc. Results relate only to the items tested or calibrated. All results are included in the report.

NOTE: THISE SAMPLES WILL BE PROPERLY DISPOSED OF AFTER 45 DAYS FROM RECEIPT OF RESULTS UNLESS OTHERWISE REQUESTED BY THE CLIENT.

Analyst: Aut	horized
COMPLIANCE WITH APPLICABLE STANDARDS AND REGULATIONS.	
I CERTIFY THAT THE ABOVE SAMPLES WERE ANALYZED IN STRICT	EPA TEST METHOD 600/R-93/116

Analyst: Date	10/1/0015	Authorized Signature:
Reported: Remarks	12/1/2015	

This report may not be reproduced, except in full, without written approval of Tec-An, Inc. These results relate only to the items tested and represent analysis of samples submitted by the client. Tec-An, Inc. is not responsible for any errors resulting from improper or incorrect sampling procedures; errors resulting from atmospheric conditions at the time of sampling or during shipment; or errors resulting from shipping conditions. All samples will be held for 45 days before disposal.











